2 nuining	10/05

CORRES. CONTROL OUTGOING LTR NO.

DOE ORDER# 05-RF-01013

DIST.	LTR	ENC
30GNAR,E.		
CROCKETT, G		
FERRERA, D.W.	Χ	X
SIACOMINI, J. J.		
GILPIN, H.E.		
INDSAY, D. C.		
SHELTON, D.C.		
TUOR, N.R.		
Degenhart, K		
Vesta, S	Χ	X

November 2, 2005

05-RF-01013

Richard J. Schassburger, Director Headquarters Cadre Project Management DOE, RFPO

TRANSMITTAL OF REVISION 1a OF DECOMMISSIONING CLOSEOUT REPORT FOR THE 776/777 CLOSURE PROJECT AND RESPONSE TO CDPHE (10/31/05) COMMENTS - DWF-107-05

Enclosed are the responses to CDPHE (10/31/05) comments on the Final Decommissioning Closeout Report for the 776/777 Closure Project, Type 3 Facility. Also enclosed is a Revision 1a to the Final Decommissioning Closeout Report for the 776/777 Closure Project.

This response to comment incorporates new text and cleaned up figures to the document, which is why the entire document was revised. For completeness Revision la is a stand-alone document.

The report is submitted to document completion of Deactivation and Decommissioning activities for the 776/777 Building Cluster. Transmittal to the Colorado Department of Health and Environment (CDPHE) and the Environmental Protection Agency (EPA), in accordance with the Rocky Flats Clean-Up Agreement (RFCA), is requested. Also, please submit color copies, as appropriate.

If you have any questions, please contact Steve Nesta at extension 6386.

AUTHORIZED CLASSIFIER

COR CONTROL X

CLASSIFICATIO

UNCLASSIFIED CONFIDENTIAL

UCNI

Demis W. Funun

Vice President and Project Manager

Remediation, Industrial D&D, and Site Services

Dennis W. Ferrera

SMN:maa

Enclosures:

As Stated

Date

IN REPLY TO RFP CC NO:

N/A

ACTION ITEM STATUS

☐ PARTIAL/OPEN

 $\beth_{\, \mathrm{CLOSED}}$

Revision 10/11/05

Original and 1 cc - Richard J. Schassburger

LTR APPROVALS:

ORIG & TYPIST INITIALS SMN:maa

John Rampe – without enclosures

ADMIN RECORD

7 2005

Kaiser-Hill Company, LLC

Rocky Flats Environmental Technology Site, 12101 Airport Way, Unit B, Broomfield, CO 80021-2583 • 303-966-7000 B776-A-000313



1) If this is Revision 1, then why isn't it a complete document? Are we supposed to remove the missing figures and sections from the Revision 0 and place them in Revision 1? Please provide instructions or a complete document.

RESPONSE:

A complete revision 1a is provided.

2) Response to previous comment 4 (Section 5) - It is stated in response that changes will be made that have not been incorporated into the Revision 1 document. Specifically, in response to the comment 4d about consistency of paragraphs 1 & 4, the response states in the 1st paragraph that all slabs basements, footers, and foundations have been removed, yet in the 4th paragraph it states that footers and foundations remain. Please modify this as previously requested to provide a consistent statement. Also, the text as provided as a response is not found in the text of the document (see 4th paragraph).

RESPONSE:

Verbiage has been corrected to reflect consistency and accuracy of what structures remain or were removed.

3) Figure 5 provided in Revision 1 is for IHSS Group 700-2 (B707) and does not appear to be associated with this document. According to the list of Tables and Figures provided, Fig 5 is supposed to be "Building 776/777 Utility Isolations.

RESPONSE:

A correct Figure 5 is provided.

4) No Fig 6 is listed in the list of Tables and Figures , yet Section 5 references Figure 6, which was supposed to have been removed.

RESPONSE:

Figure 6 has been deleted, and references to such have been corrected.

5) Request that fig 5, as provided in Revision 0, be modified to actually show the lines and infrastructure and not cover up the buildings and infrastructure with the discussions.

RESPONSE:

Figure 5 is modified to show structures.

6) Please modify all figures to properly reflect the final conditions at this site. Figure 4 (also, fig 5 in Revision 0) shows the OPWLs between B776/777 and B730 to be remaining. However this should conform to the ER IHSS Group 700-3 fig 4, which shows these OPWLs removed. Otherwise, please provide consistent information between these documents and figures properly showing all removed and remaining infrastructure.

RESPONSE:

Corrected figure is provided.

7) Previous Revision 0 included figure 6 which shows remaining footers and foundation walls remaining associated with B776 and 777. Although this figure appears to have been deleted, it appears to also show that the other buildings associated with this Report remain and have not been removed. This figure also shows that B778 remains, as well as parts of B776/777 and B707. If this figure is to be provided for the B707 Closeout Report, please correct as appropriate per our pervious comments related to the B707 Closeout Report, as well as associated with the B776/777 Closeout Report.



RESPONSE:

The drawing Figure 6 is deleted. However, the figure provided in the B707 Closeout Report clearly denotes the B707 portion of concern, and does not carry over to B776/777.

